



LightSYS+ USB-C Driver for Windows 10

1. Unzip (extract) the downloaded ZIP file to your computer
2. Right click the Windows logo on the bottom left of your screen
3. Left click [Device Manager]
4. Plug USB-A cable into your computer and the other end USB-C into the LightSYS+
5. Windows will attempt to install the LightSYS+ USB-C driver.

- 6a. If this is successful, you will see addition inside 'Ports (COM & LPT)' with 'Port Number'
- 6a. If not successful, inside the device manager box, right click the unknown device, choose to update driver, choose 'browse', then navigate to the folder where you saved the files and click [Next]